

## **HENKOVAC TRAY SEALERS:**

## EASY AND QUICK MOULD CHANGE, EASY ACCESS, EASY TO CLEAN

"Packaging of meat, vegetables, fruit, ready made meals portioned in practical trays with a professional presentation"

The TPS 1000 and TPS 2000 are especially designed for easy and fast mould changes which consists off relatively light components. The transparant cover allows quick and full access for the mould change, loading and guiding the film and thorough cleaning of the machine. The TPS 2000 has 2 moulds which doubles the production capacity compared to the TPS 1000 or adds flexibility with the installation of 2 different moulds. This only requires changing the settings at the control panel for switching to a different tray dimension. The TPS range can be equipped with a special oxygen Busch pump for gasflush > 21%, a photocell for centering printed film. The loading area can be extended, the exit belt can be motorized and the control unit has connections for auxiliary equipment.



## **SPECIFICATIONS** TRAY SEALERS

	MACHINE DIMENSION	WORK HEIGHT	PUMP	CYCLE TIME	VOLTAGE*	POWER CONSUMPTION	AIR PRESSURE REQUIRED	WEIGHT
TPS 1000	3400×1100×1500	850	100 m³	10-15 sec	400V-3-50Hz	6 kw	6 bar	950 kg
TPS 2000	4600 x 1100 x 1500	850	160 m³	10-15 sec	400V-3-50 Hz	10 kw	6 bar	1100 kg
	MAX DIMENSION TRAY	MAX HEIGHT TRAY	MAX WID	TH FILM	MAX DIAMETER FILM	ROLL CORE DIAM	ETER FILM ROLL	
TPS 1000	424 x 266	130	48	30	440		76	
TPS 2000	2X 424 x 266	130	480		440		76	

Dimensions in mm \*Machines can be supplied with all worldwide voltages applicable

## **MAXIMUM** TRAY DIMENSIONS

MOULD CONFIGURATION TPS 1000 & TPS 2000 (LXDXH)							
1:1	424 x 266 x 130						
1:2	209,5 x 266 x 130						
1:3	127 x 266 x 130						
1:4	90 x 266 x 130						
1 x round	Ø 336						
2 x round	Ø 209,5						
3 x round	Ø 127						
4 x round	Ø 90,25						

Dimensions in mm